

<b>H O N D A</b>	Compatible model	Carrier part No.
	CBR1100XX / CB1300SF (till '02)	<b>RY591H01</b>
	CB1300SF ('03 till '09)	<b>RY591H03</b>
	HORNET250 / 600	<b>RY591H02</b>
	CRF250L / M / RALLY	<b>RY59129</b>
	XR250(from '03) / MOTARD, S-XR250 / BAJA, XR250R (ME08), XR400R / MOTARD	<b>RY59101</b>
	CRM250R (from '94) / AR	<b>RY59102</b>
	XLR250R / BAJA	<b>RY59115</b>
	XR230 (till '07) *Not suitable for sissy bars	<b>RY59124</b>
	SL230 *Not suitable for sissy bars	<b>RY59107</b>
	FTR223	<b>RY59117</b>
	XR100 / 50 MOTARD	<b>RY59123</b>
	CRM80 / 50	<b>RY59103</b>
	APE50 (till '07)	<b>RY59118</b>
<b>Y A M A H A</b>	Compatible model	Carrier part No.
	XJR1300 / 1200 *Not suitable for sissy bars	<b>RY591Y01</b>
	V-MAX 1200	<b>RY591Y02</b>
	WR250R / X *Not suitable for sissy bars *Need to drill holes in the fender to mount.	<b>RY59126</b>
	TT250R	<b>RY59109</b>
	TT250 Raid *Not suitable for sissy bars	<b>RY59114</b>
	SEROW250 (till '17, from '18) · XT250X	<b>RY59125</b>
	DT230 LANZA	<b>RY59112</b>
	SEROW225 (with self starter)	<b>RY59105</b>
	TW225	<b>RY59122</b>
<b>S U Z U K I</b>	Compatible model	Carrier part No.
	GSX1400	<b>RY591S01</b>
	GSX1300R HAYABUSA (till '07)	<b>RY591S02</b>
	GSX1300R HAYABUSA (from '08)	<b>RY591S03</b>
	DR-Z400S / SM *Not suitable for sissy bars	<b>RY59116</b>
	DR250R · DJEBEL250XC	<b>RY59106</b>
	250SB	<b>RY59104</b>
	RMX250S(from '96)	<b>RY59110</b>
	VANVAN200(till '03)	<b>RY59120</b>
<b>K A W A S A K I</b>	Compatible model	Carrier part No.
	ZRX1200 / S / R · ZRX1100 / II	<b>RY591K01</b>
	ZZ-R1100D	<b>RY591K02</b>
	GPZ900R / 750R	<b>RY591K03</b>
	ZEPHYR400 / $\chi$	<b>RY591K04</b>
	ZEPHYR1100	<b>RY591K05</b>
	ZZ-R1200 *Not suitable for sissy bars	<b>RY591K06</b>
	W800 / W650 / W400	<b>RY591K07</b>
	KLX125 · D-TRACKER125	<b>RY59128</b>
	KLX250 (till '08) · D-TRACKER X (from '08)	<b>RY59127</b>
	KLX250 / SR / ES (till '07), · D-TRACKER (from '07)	<b>RY59104</b>
	SUPER SHERPA	<b>RY59113</b>
	250TR	<b>RY59119</b>
	KSR110 (from '08)	<b>RY59121</b>
	KSR I / II	<b>RY59108</b>

- \*Note that the anodized color tone partly differs, because the welded parts of the carrier, the attached assist bars, and the mounted collar are made of different types of aluminum.
- \*If this product is mounted on a vehicle with a genuine tail bag, it may not be possible to attach the bag to the vehicle.
- \*Assist bar cannot attached to the carrier for on-road models.
- \*Do not mount a box on the carrier, because it may cause damage to both the carrier and the vehicle regardless of its weight and size.
- \*Because of slight variations in dimensions of the carrier or vehicle, it may not be possible to remove the seat easily while the carrier is mounted.
- \*The load capacity of the RALLY 591 carrier is 2 kg.